

Menu


HISTORY FILE MAP for year 1999

Realtime

Playback

Recalled Realtime

Recalled Playback



18m RT 2048bps and 6m RT 512bps data lost due to DSS42 stuck subreflector. Replacement DSS43 track ended earlier than the originally scheduled DSS42 track. DR A04113 refers.

DSU carryover

28m RT 1024ps data lost due to DSS34 antenna power failure. DSS45 came up quickly to support, reducing data losses considerably. DR A04114 refers.